

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 14 Apr 2021

Preliminary Advice

Vehicle No	: SLB1656Z	Accident Date	: 03/04/2021
Make	: AUDI Q3	Policy No.	: 2070119748
Assignment Date	: 07/04/2021	Excess	: S\$400.00
Date of Inspection	: 06/04/2021	Est. Duration of Repair	: 10
Inspection At	: 24 BENOI SECTOR		
	REPAIRER : PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	74,257.00	(ESTIMATE \$68,872.00 + SUPPLEMENTARY \$5,385.00)
Revised Amount	:S\$	50,154.00	
Check Items (Estimated)	:S\$	8,261.00	
Total	:S\$	58,415.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	139,000.00
COE / PARF Rebate	:S\$	57,848.00
Salvage Value	:S\$	
Margin for Repair	:S\$	81,152.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :