

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd					
60 Woodlands Industrial Parl	E4, Singapore 757705				
AX Number : 63685592					
Estimator Telephone Number	68662623				
Accident Reporting Number	68662672				

Date Generated : 05/04/2021

	Section A - Accident	Details					
Registration Number	SMB5003U						
Case Reference Number	BUS/03/21/5066						
Registration Date	9/10/2014						
Company Type	SMRT Buses LId						
Make	ALEXANDER DENNIS						
Model	ENVIRO 500						
Name of Driver		Lee Peng Wah					
Type of Accident	Head To Side						
Accident Date and Time	3/30/2021 10:43 PM	CONTROL SPACE SCHOOLSES					
Accident Reported Date and Time	3/30/2021 11:45 PM						
Is Surveyor Required?	No						
Survey by							
Vehicle is Towed Back?	No						
Towed Back Date and Time							
Replacement Vehicle issued?	No						
Job Card Number	- 175						
Special Instruction to ARC,if any	SMB5003U - LEFT REAR PORT SLE4912Z (TP) - INSURED WITH	SMB5003U - LEFT REAR PORTION SI F40127 (TP) - INSURED WITH AIG					
Prepared Date and Time	4/3/2021 1:40 PM						
Chassis Number	SFD76CLR5EMTL3463	SFD76CLR5EMTL3483					
Mileage							
Work Shop							
Repair Completion Date and Time							
	Section B - Summary of Rep	nair Fatimates					
Summary of Repair Estimates	Couldn't Callinary of No.	Tall Estillates					
	Quotation from ARC	Adjusted by Surveyor, if applicable					
	\$1,060.00	\$0.00					
Total Spray Cost	\$878.00	\$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost	\$878.00 \$98.55	\$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost	\$878.00 \$98.55 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST	\$878.00 \$98.55 \$0.00 \$2,036.55	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim 05/04/2021 9:28 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00					
Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim	\$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim 05/04/2021 9:28 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	\$878.00 \$98.55 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim 05/04/2021 9:28 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00					
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$878.00 \$98.65 \$0.00 \$2,036.55 \$0.00 3.0 Kim Bock Sim 05/04/2021 9:28 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00					

	Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number		
Quotation Date		Invoice Date		
Invoice Amount		Prepared Date		



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Telephone Number 68662623 Accident Reporting Number 68662672

Date Generated: 05/04/2021 User ID : KimBock

12			Se	ction D - Deta	ils of Repair E	stimates		and the second second second		
Part 1 - Labo	ur Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR REAR LHS PORTION			\$1,060.00			530				
Total Labour			\$1,060.00	\$1,060.00						
Part 2 - Spra	y Painting & P	Panel Beating Rela	ited Works		_				Table 24 (A)	
Job Scope			Quotation from ARC			Adjusted by Surveyor, if applicable				
TO PUTTY & F	RESPRAY			\$878.00				700		
Total Spray Pa	al Spray Painting & Panel Beating \$878.00					100				
Part 3 - Other	Costs - Acci	dent and Accident	Repair Related Expe	ense						
Job Scape			Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Co	sts									
Part 4 - Span	Parts / Mater	rial Usage							•	
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
6011891	Body		COVER:4 WAY VALVE,DOOR,MAN A22,A24,A95	1.00	\$109.50	10.00	\$98.55		/Chy.	
Total					\$109.50		\$98.55			
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off					. Marc		
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
	1				Series and Control			-		

Repair dy - 2dy)
Sun Pin (Llkl)
05/04/2021
After print
Thurk pupu

Signature: Acknowledged by Repairer

is subject to final approval from Insurance Company • Supplementary item(z) must be resurveyed and

- No illegal modification(s) is allowed • Third party survey is on a "Without Prejudice" basis

 - Parts prices are subject to confirmation
 - To display damaged part(s) during resurvey

 - To resurvey before/after spray painting
 - the Repairer of the following: LKK Auto Consultants hence notify

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Page 2 of 2