



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21004401/Evf3e2	
			Date: 27/05/2021	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SGJ 8869Y
	Policy No.	Z21VP05028188	Coverage (\$)	0.00
	Claim No.	21/21/21/VP05/024405	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	27/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 A	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2040312A773730	Colour	WHITE
	Odometer	107248 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R17	CONTINENTAL	4 mm
	L/H Front Tyre	245/40 R17	CONTINENTAL	4 mm
	R/H Rear Tyre	245/40 R17	CONTINENTAL	4 mm
	L/H Rear Tyre	245/40 R17	CONTINENTAL	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/03/2021	Inspection Date	13/04/2021
	Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks				
	A) THE MARKET VALUE IS S\$41,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	