

Estimate

05/04/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Steve (LKK)
13/4/21, 1.09pm
OO- AL AL
EXCISE - ?
L/S
M AL M
3 dys

Page # :- 1
Veh # :- SGJ8869Y
Veh Model :- MERCEDES BENZ C180 A
Estimate# :- CK421731
Claim # :-
ACC. Date :- 27/03/21
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	SIDE MIRROR RH / CUT ? / DR	1	PC 650.00	650.00 ✓
2.	SIDE MIRROR COVER RH	1	PC 250.00	250.00 ✓
3.	SIDE MIRROR GLASS RH - OR	1	PC 880.00	880.00 ✓
4.	SIDE MIRROR LOWER COVE RH / CUT	1	PC 55.00	55.00 ✓
5.	FRONT FENDER RH - OO	1	PC 450.00	450.00 ✓
6.	FRONT FENDER CHROME RH - MC	1	PC 35.00	35.00 ✓
7.	FRONT DOOR RH - TO REPAIR X R	1	PC	
8.	FRONT BUMPER - TO REPAIR X	1	PC	
LIST TOTAL S\$				2,320.00
15% COST PLUS S\$				348.00
				1815
				+ 15%
				P- 2087.25
				L- 800
				2887.25
				L/S - 2309.80
				= 2300
LABOUR :				300
TO REPAIR FRONT DOOR RH, FRONT BUMPER				
TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN				
& REALIGN AFFECTED AREAS				450.00
TO SPRAY FRONT BUMPER, FRONT FENDER RH,				
FRONT DOOR RH, SIDE MIRROR RH AND AFFECTED				
AREAS				500
LABOUR TOTAL S\$				750.00
				1,200.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,868.00

GST @ 7 % 270.76

AMOUNT DUE S\$ 4,138.76

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

bizSAFE