

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 07 Apr 2021

Preliminary Advice

Vehicle No	: SMX9556Z	Accident Date	: 31/03/2021
Make	: MERCEDES-BENZ 200E	Policy No.	: DMPCSNW00188352000
Assignment Date	: 07/04/2021	Excess	: S\$0.00
Date of Inspection	: 07/04/2021	Est. Duration of Repair	: 9
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,482.75
Revised Amount	:S\$	13,566.79
Check Items (Estimated)	:S\$	8,955.96
Total	:S\$	22,522.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	172,000.00
COE / PARF Rebate	:S\$	78,250.00
Salvage Value	:S\$	
Margin for Repair	:S\$	93,750.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :