



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2021

ESTIMATE

NO : QUOT202103-000069(00)

DATE : 13/04/2021

POLICY NO : 999995580

VEH REG NO : SLP7899B

MAKE/MODEL : MERCEDES BENZ GLC250
4MATIC (R18 LED)

CHASSIS NO : WDC2539462F226286

ENGINE NO : 27492030970746

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLP7899B

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Front grille svc	1	215.00	215.00
2 Front bumper fog lamp cover - LH	1	55.00	55.00
			270.00
		Add 10%	27.00
			297.00
		TOTAL	S\$ 297.00
		ADD GST @ 7%	20.79
		GRAND TOTAL	S\$ 317.79

SINGAPORE DOLLAR THREE HUNDRED SEVENTEEN AND CENTS SEVENTY-NINE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE