

Date: 06.04.2021
Vehicle No: SLT1444Z
Model: TOYOTA PRIUS HYBRID 1.8S
Chassis: ZVW506048674-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SKH3172U
Date of Accident: 06.04.2021

Not Notified
1/1 by B
7 days *Resurvey After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER	1		\$616.00	?
2	FRONT BUMPER SIDE BRACKET RH	1		<i>Prt</i> \$82.00	✓
3	FRONT HEADLAMP RH	1		\$2,637.00	?
4	FRONT FENDER RH	1		<i>R</i> \$877.00	X
5	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>Pr</i> \$55.00	✓
6	FRONT FENDER INNER LINER RH	1		<i>Pr</i> \$202.00	X
7	FRONT PILLAR GARNISH COVER RH	1		<i>Pr</i> \$88.00	X
8	FRONT SIDE MIRROR ASSEMBLY RH	1		<i>CM</i> \$1,173.00	✓
9	FRONT SIDE MIRROR COVER RH	1		<i>R</i> \$90.00	X
10	SIDE SKIRT RH	1		\$594.00	?
11	FRONT DOOR RH	1	<i>Pr / wrap</i>	\$1,249.00	✓
12	FRONT DOOR FRAME RUBBER RH	1		<i>Pr</i> \$223.00	X
13	FRONT DOOR HANDLE RH	1		<i>Pr</i> \$378.00	X
14	FRONT RIM RH	1		<i>Pr</i> \$1,555.00	✓
15	FRONT ABSORBER RH	1		\$472.00	?
16	FRONT KNUCKLE ARM RH	1		\$555.00	?
17	FRONT WHEEL BEARING RH	1		\$554.00	?
18	FRONT CONTROL ARM RH	1		\$631.00	?
19	FRONT TIE ROD END RH	1		\$155.00	?
20	REAR DOOR RH	1	<i>Pr / wrap</i>	\$1,243.00	✓
21	REAR DOOR FRAME RUBBER RH	1		<i>Pr</i> \$175.00	X
22	REAR DOOR HANDLE RH	1		<i>Pr</i> \$278.00	X
23	REAR FENDER RH	1		<i>R</i> \$900.00	X
24	REAR FENDER INNER LINER RH	1		<i>Pr</i> \$186.00	X
25	REAR BUMPER	1		\$542.00	?
26	REAR BUMPER SIDE BRACKET RH	1		<i>Pr</i> \$112.00	X
27	REAR TAIL LAMP RH	1		\$478.00	?
28	FRONT BONNET	1		REPAIR	
				SUB TOTAL	\$16,100.00
				LESS 25%	-\$4,025.00
				PARTS TOTAL	\$12,075.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Head office: 8 Kung Chong Road Singapore 150143 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch (Motor Insurance Claims): Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Branch: 9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 0010 | Fax: (+65) 6481 1093



Date: 06.04.2021
Vehicle No: SLT1444Z
Model: TOYOTA PRIUS HYBRID 1.8S
Chassis: ZVW506048674-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SKH3172U
Date of Accident: 06.04.2021

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		na \$50.00 ✓
2	FRONT FENDER INNER LINER CLIPS RH	1		na \$30.00 X
3	FRONT DOOR INNER TRIM CLIPS RH	1		\$40.00 ?
4	REAR DOOR INNER TRIM CLIPS RH	1		\$40.00 ?
5	REAR FENDER INNER LINER CLIPS RH	1		na \$30.00 X
6	REAR BUMPER CLIPS	1		na \$50.00 ✓
S/N TOTAL				\$240.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	\$1,600.00	800
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT BONNET, FRONT DOOR RH, SIDE SKIRT RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.	\$1,800.00	1400
LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.	\$120.00	60
LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.	\$120.00	60
LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT RIM RH, FRONT ABSORBER RH, FRONT CONTROL ARM RH, FRONT KNUCKLE ARM & ETC.	\$250.00	?
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	60
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	30
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	60
LABOUR TOTAL		\$4,420.00

TingAn

TOTAL

\$16,735.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0019 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

