



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 29/03/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	16/03/2017	SLL9508M	0	60979	66TPSLL9508M/290321
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3002007645		2NRX131423	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHB5973D ACC DATE:26/03/21 DRIVE IN:29/03/21 @ 1000 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				180.00	
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				2160.00	
4	B	BP-RES2 RESRPAY ACC AFF AREA				1770.00	
5	1	S53812-K0020 L/FRONT FENDER PANEL	1.00	706.80		706.80	
6	2	S53876-0D380 LINER, FR FENDER, LH	1.00	303.40		303.40	
7	3	S52119-0U920 COVER, FR BUMPER, L/	1.00	495.70		495.70	
8	4	S52536-0D190 RETAINER, FR BUMPER	1.00	68.70		68.70	
9	5	S81150-0D831 HEADLAMP ASSY, LH	1.00	608.70		608.70	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 6,393.30
					Parts 2,183.30		GST 7.00% 447.53
					Labour 4,210.00		
					Sublet 0.00		
					Lubrication/Fluid 0.00		
					Others 0.00		Less 0.00
					Amount Due 6,840.83		

Company Copy