

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMA3150X (Insd veh)	Model:	TOYOTA HIACE 3.0 D GL (A)
	PC82H (TP veh)		
Date of Accident:	07/04/2021		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$			9,378.51	
Final Repair Cost	:	\$			3,745.00	
Loss of Use	:	\$			900.00	6.00 days at \$150.00 per day
Rental (if any)	:	\$			0.00	days
LTA / GIA Search Fee	:	\$			7.45	
Others:	:	\$			0.00	
	:	\$				
Final Settlement Sum	:	\$			4,652.45	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For <u>Non GIA Registered Workshop</u>:			Agreed Liability _____ 100 _____ (%)			
B) For <u>GIA Registered Workshop</u>:			BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%)			Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Ryder Auto Pte Ltd	: \$	4,652.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

17 Aug 2021
Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)