

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
 SHD9046T

AAD2104-006

Not Notified
Reborn B4 paint
8964.73

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

06 APR 2021

SHD9046T
 JTDKB3FUX03076032
 TOYOTA
 PRIUS
 02/04/2021
 AIG
 01/11/2018

PART	LIST	PRICE	STATUS
1 LENS AND BODY, REAR LAMP, RH	\$ SLE	502.00	X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$ SLE	451.80	X
1 PANEL SUB-ASSY, QUARTER, RH	\$ R	871.50	X
1 LINER, REAR WHEEL HOUSE, RH	\$ S	139.80	X
1 COVER, REAR BUMPER	\$ MYOM	442.60	✓
1 FILLER, REAR BUMPER EXTENSION, RH	\$ MY COM	123.70	✓
1 GUARD, REAR BUMPER, CENTER	\$ S	576.30	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ R	332.70	X
TOTAL	\$	3,440.40	
25%	\$	860.10	
	\$	2,580.30	

Special Nett	PRICE	STATUS
1 FENDER LINER CLIP	\$ NN	75.00 X
1 FENDER CLIP	\$ NN	75.00 X
1 REAR BUMPER CLIP	\$ NN	65.00 50mm
1 END PANEL INNER TRIM CLIP	\$ NN	60.00
1 TYRE	\$ S	350.00
1 RIM	\$ S	1,879.40
1 HUM CAP	\$ S	211.50
2 WINDSCREEN SEALANT	\$ NN	150.00
1 WINDSCREEN MOULDING	\$ NN	200.00
1 WINDSCREEN INNER SPONGE SEAL	\$ NN	130.00
TOTAL	\$	3,195.90
TOTAL PARTS	\$	5,776.20

LABOUR

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6257 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
 SHD9046T

AAD2104-006

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nu</i> 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>2801</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>2001</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	X
	TOTAL	\$ 4,790.00	
	Over All Total	\$ 10,566.20	

(PART-BY-PART) Repair Days

10 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: