



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004450/Quf3n2	
			Date: 23/04/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 77C	Veh. Inspected	SMM 8046T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/03/21/2077	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	07/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8 A	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	ZNE100313237	Colour	BLUE
	Odometer	131576 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	235/45 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/45 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/45 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/03/2021	Inspection Date	08/04/2021
	Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	