

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
Premier@Kaki Bukit S(415875)
Tel : 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 7-Apr-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: GBK5969R
ADDRESS	:	MODEL / MAKE	: NISSAN NV200
TEL. NO.	:	CHASSIS NO.	: JN1YAAM20Z0001019
<u>OWNER INSURANCE</u>		<u>ACCIDENT DETAIL</u>	
POLICY NO.	: DMCG20010949	DATE	: 3-Apr-21
		TIME	: 18:10HRS

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	REAR TAILGATE <i>Distorted</i>	1	\$ 1,835.00	\$ 1,835.00
2	REAR TAILGATE LOGO EMBLEM <i>3</i>	1	\$ 59.70	\$ 59.70
3	REAR TAILGATE NV200 EMBLEM <i>1pc</i>	1	\$ 87.00	\$ 87.00
4	REAR TAILGATE VANTTE EMBLEM	1	\$ 69.50	\$ 69.50
5	REAR TAILGATE OUTER GARNISH <i>crushed</i>	1	\$ 363.00	\$ 363.00
6	REAR TAILGATE INNER TRIM BOARD <i>Dehnd</i>	1	\$ 180.50	\$ 180.50
7	REAR TAILGATE MECHANISM LOCK <i>Dehnd</i>	1	\$ 261.00	\$ 261.00
8	REAR TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 93.80	\$ 93.80
9	REAR TAILLAMP LH/RH <i>1pc</i>	1	\$ 258.70	\$ 258.70
10	REAR BUMPER <i>Dehnd</i>	1	\$ 481.10	\$ 481.10
11	REAR BUMPER SIDE RETAINER LH/RH <i>1pc</i>	2	\$ 36.30	\$ 72.60
12	REAR BUMPER TOW HOOK COVER <i>1pc</i>	1	\$ 26.10	\$ 26.10
13	REAR END PANEL OUTER <i>Distorted</i>	1	\$ 162.40	\$ 162.40
14	REAR END PANEL INNER <i>Distorted</i>	1	\$ 644.00	\$ 644.00
15	REAR END PANEL INNER TOP GARNISH <i>crushed</i>	1	\$ 83.50	\$ 83.50
16	REAR END PANEL TAILGATE LOCK STRIKER <i>1pc</i>	1	\$ 47.10	\$ 47.10
17	REAR FLOOR PANEL <i>Repis</i>	1	\$ 1,228.40	\$ 1,228.40
18	REAR FLOOR PANEL TOP CARMAT <i>1pc</i>	1	\$ 438.00	\$ 438.00
19	SPARE TYRE BRACKET <i>Bed</i>	1	\$ 251.10	\$ 251.10
20	SPARE TYRE SCREW LOCK SET <i>1pc Bed</i>	1	\$ 108.20	\$ 108.20

21 REAR TAILGATE INNER HANDLE *# 35* ✓

22 REAR BUMPER INNER SPONGE *# 118* ✓

TOTAL PRICE	\$ 6,750.70
LESS -10%	\$ (675.07)
SUB TOTAL PRICE	\$ 6,075.63

crushed

4905.40

4414.86

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER SET <i>nee</i>	1	\$ 100.00	\$ 100.00	60
2	REAR TAILGATE 70 KM/H STICKER <i>3 nee</i>	1	\$ 50.00	\$ 50.00	15
3	REAR TAILGATE 4 PAX STICKER	1	\$ 50.00	\$ 50.00	15
4	REAR TAILGATE NUMBER PLATE WITH CASING SET <i>nee</i>	1	\$ 65.00	\$ 65.00	+
5	REAR TAILGATE OUTER GARNISH CLIPS SET <i>nee</i>	1	\$ 50.00	\$ 50.00	20
6	REAR TAILGATE INNER TRIM BOARD CLIPS SET nee NEC	1	\$ 60.00	\$ 60.00	30
7	REAR TAILLAMP CLIPS SET LH/RH <i>nee nee</i>	1	\$ 40.00	\$ 40.00	+
8	REAR BUMPER CLIPS SET <i>nee</i>	1	\$ 80.00	\$ 80.00	30
9	REAR BUMPER REVERSE SENSOR SET <i>Damaged</i>	1	\$ 280.00	\$ 280.00	200
10	REAR END PANEL SEALANT <i>nee</i>	1	\$ 100.00	\$ 100.00	60
11	REAR END PANEL INNER TOP GARNISH CLIPS SET <i>nee</i>	1	\$ 40.00	\$ 40.00	20
12	REAR FLOOR PANEL SEALANT <i>nee nee</i>	1	\$ 150.00	\$ 150.00	+

450

TOTAL

\$ 1,065.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,000.00	1200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	600	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 125.00	80	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	50	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 180.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	+	

TOTAL

\$ 3,545.00

2020

QUOTATION SUMMARY
ESTIMATE REPORT

PAGE 03

TOTAL PARTS COST	:	\$	7,140.63
TOTAL LABOUR COST	:	\$	3,545.00
TOTAL REPAIR COST	:	\$	10,685.63

10,823.33

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMPSUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	
CONTACT NUMBER	:	
EMAIL ADDRESS	:	

Adrian Lj

1/s 08/04/21

07 Days .

total: 6884.86.

1/s: 5.5K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: