

BIG WHEELS PTE LTD

WORKSHOP ADDRESS: NO. 10 BUROH STREET #04-26 WEST CONNECT BUILDING SINGAPORE 627564 EMAIL: ADMIN@BIGWHEELS.SG COMPANY& GST REGISTRATION NO: 201824297N

Sales Quotation

CUSTOMER : Call Lade Enterprises Pte Ltd

102F Pasir Panjang Road #02-02,

Citilink Warehouse Complex,

Singapore 118 530

ATTN : Mr. Chua

QUOTATION NO : SQ/CL/4358

DATE : 05 APR 2021

VEHICLE : XE4358G

MODEL : SCANIA P400

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
ORIGIN	IAL PARTS	9		
1.	Windscreen	1	\$\$1,660.56	\$\$1,660.56
2.	Cab Corner LHS, Outer	1	\$\$1,203.16	\$\$1,203.16
3.	Cab Corner LHS, Inner	1	\$\$123.42	\$\$123.42
4.	Space Frame	1	\$\$2,751.33	\$\$2,751.33
5.	Door Frame LHS	1	\$\$4,877.03	\$\$4,877.03
6.	Door Stop	1	\$\$503.98	\$\$503.98
7.	Door Glass LHS	1	\$\$512.78	\$\$512.78
8.	Window Winder LHS	1	\$\$1,857.90	\$\$1,857.90
9.	Window Motor LHS	1	\$\$1,026.34	\$\$1,026.34
10.	Door Handle LHS	1	\$\$253.00	\$\$253.00
11.	Door Lock LHS	1	\$\$463.38	\$\$463.38
12.	Boarding Step Structure LHS	1	\$\$1,150.60	\$\$1,150.60
13.	Step Plate	1	\$\$132.00	\$\$132.00
14.	Step Plate, Lower	1	\$\$93.50	\$\$93.50
15.	Step Well Case Cover LHS	1	\$\$378.37	\$\$378.37
16.	Casing LHS	1	\$\$93.50	\$\$93.50
17.	Cover LHS	1	\$\$132.00	\$\$132.00
18.	Mudguard Front LHS	1	\$\$619.16	\$\$619.16
19.	Mudguard Front RHS	1	\$\$619.16	\$\$619.16
20.	Mudguard Seal Front LHS	1	\$\$219.57	\$\$219.57
21.	A Pillar LHS	1	\$\$275.00	\$\$275.00
22.	Casing LHS	1	\$\$49.50	\$\$49.50
23.	Side Mirror Assy, LHS	1	\$\$1,595.00	\$\$1,595.00
24.	Sun Visor, Lower	1	\$\$1,595.00	\$\$1,595.00
25.	Sun Visor, Top	1	, S\$511.50	\$\$511.50
26.	Bracket, Kerb Observation Mirror	1	\$\$49.50	\$\$49.50
27.	Close Proximity Mirror (Door)	1	\$\$132.00	\$\$132.00
28.	Lock Bracket	2	\$\$132.00	\$\$264.00
29.	Headlamp w/ Signal & Wire LHS	1	\$\$688.53	\$\$688.53
30.	Cabin Shock Absorber, Rear	2	\$\$752.49	\$\$1,504.98
31.	Side Wall Structure LHS	1	\$\$2,389.38	\$\$2,389.38
32.	Roof Panel	1	\$\$3,817.36	S\$3,817.36
33.	Roof Panel LHS	1	\$\$1,167.28	\$\$1,167.28
34.	Door Trim	1	\$\$865.88	\$\$865.88
35.	Sun Visor	1	\$\$511.31	\$\$511.31

Total Parts Costs: \$\$34,086.93



BIG WHEELS PTE LTD

WORKSHOP ADDRESS: NO. 10 BUROH STREET #04-26 WEST CONNECT BUILDING SINGAPORE 627564 EMAIL: ADMIN@BIGWHEELS.SG COMPANY & GST REGISTRATION NO: 201824297N

Sales Quotation

CUSTOMER : Call Lade Enterprises Pte Ltd

102F Pasir Panjang Road #02-02,

Citilink Warehouse Complex,

Singapore 118 530

ATTN

: Mr. Chua

QUOTATION NO : SQ/CL/4358

DATE

: 05 APR 2021

VEHICLE

: XE4358G

MODEL

: SCANIA P400

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LABOUR			
Carry out overall vehicle checking & diagnostic Dismantle & install above mentioned spare parts Cut & remove dented panel (top, front, side) Carry out realignment - panel, cabin			
Pull out and knock vehicle frame, front & side bumper, cab	1	564 400	564.400
corner, front & side cover Remove and rework inner door upholstery Knock and straighten pillar, vehicle chassis	1	S\$4,400	S\$4,400
Spray painting of affected areas including cab corner, top & front & side panel (2 colours, exterior & interior) Logo writing (LHS door, roof top)			

Total Labour Costs:

\$\$4,400.00

Total w/o GST:	\$\$38,486.93
GST (7%):	\$\$2,694.09
Total Costs:	\$\$41,181.02

TOTAL: FORTY-ONE THOUSAND ONE HUNDRED EIGHTY-ONE DOLLARS AND TWO CENTS ONLY**

Terms and conditions:

- 1. All prices are quoted in SG dollar.
- 2. Validity: 30 days.
- 3. The quotation for parts & labour are estimation based on the repair required, if any additional parts & labour are required during the repair that exceed 10% of the total quote we will inform you of the cost for further approval.
- 4. If you are agreeable with this quotation, kindly endorse and fax back this quotation in order for us to proceed with the repair.

Thank you & Regards,

Big Wheels Pte Ltd

We confirm acceptance of the above quotation

(Signature & Company Stamp)