

(08/11/13) wef

ASS. REC. BY: *Merous*

REF:

*CC4/ASM 21004471/4ba3*ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SD 7 5110E

at Workshop m/s

zoom

of

Insured:

XB 6988R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$70k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

013h

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

*rep. etc.**car until 15-8-2030 LTA \$30781**21/4/14 1/5 \$7800 confirmed with Eilin*Veh No: *SPT 5110E*

Yr Regn:

*16/8/10*Type: *M. Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

*BMW 523i*c.c *2497*

Colour:

3/cck

A/C: Insured / Std / NI / NA

Sp. Reading

242831

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*WBAFP32030C545335*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

*245/45 R18*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU *(PIR)* SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/4/21

D.O.I.

8/4/21

Survey held at

Des. of Damages: *Rear* / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) *S + RS* SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Lee Jasper

Car Number: SDT5110E

Model : BMW 523i

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorized
Rear
2/5 \$7800
7 days

Parts / Material :

1	Rear Bumper	D/S 531	\$ 1,786.50	—
2	Rear Bumper Side Guide @ 112.20	Bent	\$ 224.40	—
3	Rear Bumper Inner Guide @ 95.60	1A	\$ 191.20	X
4	Rear Bumper Centre Inner Bracket	one	\$ 320.40	—
5	Rear Bumper Reflector @ 195.00	1A	\$ 390.00	X
6	Rear Bumper Centre Lower Garnish	VF	\$ 895.20	X
7	Rear Bumper Reinforcement	Bent	\$ 679.80	—
8	Rear Bumper Sensor (ORI) @ 263.10	should 640-53 225x2=450	\$ 1,052.40	2pc
9	Rear Bumper Sensor Holder	1A	\$ 115.00	X
10	Rear Bumper Tow Garnish	710A 38-00	\$ 110.00	—
11	Rear Bumper Bumper Clips (SET)	new	\$ 60.00	—
12	Rear Bootlid Panel	Bent/Burr	\$ 2,180.40	—
13	Rear Bootlid Inner Lock	1A	\$ 495.70	—
14	Rear Bootlid Lock Sensor	1A	\$ 517.80	X
15	Rear Bootlid Logo	new	\$ 128.00	—
16	Rear Bootlid Emblem (523i)	new	\$ 137.00	—
17	Rear Bootlid Weather Strip	1A	\$ 468.60	—
18	Rear Bootlid Lamp @ 783.00	1A	\$ 1,566.00	X
19	Rear Taillamps @ 1186.00	new one	\$ 2,372.00	1pc
20	Rear Exhaust Heat Shield	1A	\$ 320.10	X
21	Rear Exhaust Chrome Muffler	1A	\$ 245.80	X
22	Rear End Panel	Bent	\$ 989.00	—
23	Rear End Panel Top Garnish	new	\$ 275.00	X
24	Rear End Panel Top Garnish Clips	1A	\$ 60.00	X
25	Rear Spare Tyre Top Board	waged	\$ 465.00	—

Parts : \$ 16,045.30

Less Parts 5% : \$ 802.26

Total Parts : \$ 15,243.03

Special Net Items :

Front Driver Seat Head-Rest Air Bag (Repair Kit)	Actual 165 S.N	\$ 987.20	—
Front Passenger Seat Head-Rest Air Bag (Repair Kit)	Actual 165 S.N	\$ 826.70	—
Rear End Panel Sealant	new	\$ 80.00	50
Rear Number Plate W/Base Garnish	1A	\$ 80.00	X

Total S/N Parts : \$ 1,973.90

P-774893
S2
P-7361.48
S.N-380.20
L 2060 9801.48

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas
To Putty, Spray Paint on Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Remove & Install Rear Bootlid Components Trim & Garnish
To Remove & Install Rear Fenders Trim, Garnish
To Remove & Replace Front Driver Seat Head-Rest Air Bag
To Remove & Replace Front Passenger Seat Head-Rest Air Bag
To Re-Programme & Reset ECU Diagnostic
To Conduct Water Leakage Test
To Remove, Install & Re-position Reverse Sensor
To Rust Proof Affected Areas

\$	1,200.00	800
\$	1,400.00	900
\$	50.00	30
\$	150.00	60
\$	150.00	80
\$	150.00	80
\$	150.00	80
✓	\$ 480.00	X
✓	\$ 150.00	X
\$	150.00	50
\$	150.00	60
Total Labour :	\$ 450.00	
	\$ 4,330.00	

TOTAL PARTS :	\$ 15,243.03
TOTAL SPECIAL NET ITEM :	\$ 1,973.90
TOTAL LABOUR :	\$ 4,330.00
TOTAL REPAIR COST :	\$ 21,546.93

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rental Car DEALS



Rental starts from
\$400/wk
Audi A1 1.0A



Rental starts from
\$2000/mth
Audi A8L 4.2FSI QU Facelift



Rental starts from
\$1400/mth
Honda Fit Hybrid Brand New

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Toyota Harrier 2.0A Elegance Panoramic At \$74.5k.



Low Mileage, Immaculate Condition, Well-maintained And In Good Condition.
Direct Owner [StarAd](#)

PRIME MOTOR & LEASING
[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

17 vehicles

bmw 523 2030

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 523 2030	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	BMW 5 Series 523i (COE till 12/2030)	\$78,800	\$8,090 /yr	16-Feb-2011	2,497 cc	125,230 km	Luxury	Available
Graded B by \$888/Month At 2.88% P.a. By GV Cars Financing! 2.5 Yr Warranty On Engine & Gearbox By GV Motorworkz. NO Hidden/Admin/Surcharge Fees. Optional Addon: New Metallic Paintwork. New Leather Seat. New Rims & Tyres. New Pioneer/Android Touchscreen Head Unit. Fro... Posted: 08-Apr-2021 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i								
	BMW 5 Series 523i Highline (COE till 08/2030)	\$78,800	\$8,400 /yr	26-Aug-2010	2,497 cc	119,461 km	Luxury	Available
Extremely Well Kept Unit! High Spec Model With Suction Door And Electric Tailgate! 100% Loan Available With Hassle Free Loan Procedure! \$0 Down Payment Available With 100% Loan Approval! Trade In Welcome! Flexible Bank/In House Financing Available With... Benefit Auto Enterprise Pte Ltd Posted: 08-Apr-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i								
	BMW 5 Series 523i Highline (COE till 12/2030)	\$78,888	\$8,110 /yr	30-Dec-2010	2,497 cc	139,770 km	Luxury	Available
Don't Miss It! Option With Touch Screen Cockpit Android Player, PML Highline Unit! 2 Careful Owners, Very Well Maintained, Wear And Tear Replaced, Warranty Available, Accident-Free! Flexible 100% Inhouse/Bank Loan/High Trade In Available, Must View! Posted: 08-Apr-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i								
	BMW 5 Series 523i (COE till 06/2030)	\$80,800	\$8,750 /yr	17-Sep-2010	2,497 cc	90,000 km	Luxury	Available
Strictly Well Maintained. Recently Spent 6K Revamped To New Original Spec With Receipt 0 Wear & Tear, New Bilstein Absorber With H&R Sports Spring. Full M5 Body Kit With Full Carbon Fibre Side Skirt, Front Lip, Spoiler, Fin, Rear Diffuser Quad Exhaust Tip, Bonnet, Kidney,... Posted: 06-Apr-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i								
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	BMW 5 Series 523i (COE till 10/2030)	\$75,998	\$7,940 /yr	06-Jan-2011	2,497 cc	-	Luxury	Available
Drive With Assurance! Genuine And Transparent Deal! Flexible Bank/In House 100% Loan/Trade-In Available! All Our Consignment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Welcome! Best Deal Assured! Visit Our Website For The... CarQuotz Singapore Posted: 06-Apr-2021 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i								
	BMW 5 Series 523i Highline (COE till 12/2030)	\$80,800	\$8,300 /yr	24-Feb-2011	2,497 cc	-	Luxury	Available
Well Maintained Highspecs Unit With Upgraded Android Headunit. Comfortable And Spacious Legroom With Huge Boot Space! Perfect Condition With No Repairs Needed Upon Purchase. No Sticky Handles/Buttons. 100% Accident Free Unit. STA Evolution Welcome For A... Posted: 05-Apr-2021 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i								

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 013H

Vehicle Details

Vehicle No.: SDT5110E
Vehicle to be Exported: No
Intended Deregistration Date: 08 Apr 2021
Vehicle Make: B.M.W.
Vehicle Model: 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 07157498N52B25AF
Chassis No.: WBAFP32030C545335
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$45,866.00
Original Registration Date: 16 Aug 2010
First Registration Date: 16 Aug 2010
Transfer Count: 0
Actual ARF Paid: \$45,866.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Aug 2030
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$32,914.00
COE Rebate Amount: \$30,781.00
Total Rebate Amount: \$30,781.00

The information contained herein is correct as at 08 Apr 2021.

OK