

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 1330071301C GS1 Reg. No. 13-3007130-1C					
Affiliated to Federation Internationale Des Experts En Automobile						
	MSIG INSURANCI	(SINGAPORE) PTE LTD		Ref:	CS/LAW21004494/f3	
	C/O: FOO KWOK I BLK 134 JURONG #04-307HSINGAP	GATEWAY ROAD		Date:	08/04/2021	
				Code:	MSG	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SLW 1898G	Veh. Inspected		SDP 5699U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	FK Ref; KCYT/R2-705-21/nn	Excess (\$)		0.00	
	Assign From	NOEL HWANG	Assign Date		22/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	21/02/2020	Inspection Date	е	01/01/1999	
	Survey held at	V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.	5a. Remarks					

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.