

## Shiau Chan (LKKAuto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Friday, 20 May 2022 11:25 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Re: CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Shiau Chan,

Audit check done for GBJ1106X without problem.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Friday, 20 May 2022 10:02 am  
**To:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Subject:** RE: CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Simon,

For your re-audit before send offer to workshop.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Sent:** Monday, 4 April 2022 12:09 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** Re: CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Shiau Chan,

Audit check done for GBJ1106X, found surveyor marking need to review.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Monday, 4 April 2022 11:38 am  
**To:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Subject:** RE: CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Mr Ho,

For your re-audit.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Sent:** Monday, 19 April 2021 3:07 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Shiau Chan,

AUDIT CHECK DONE FOR GBJ1106X, FOUND REAR DAMAGED WASN'T MENTION IN THE SAS.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 19 April, 2021 2:17 PM  
**To:** Simon Ho (LKKAuto)  
**Subject:** CTI-OD GBJ 1106X SURVEYED BY GUO QIANG

Dear Simon,

For your audit.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)