

1	of 2 ?	100%	Find Next
---	--------	------	-------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Ref: CS/CTI21004525/R1qf3 Date: 09/04/2021 Code: CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBG 6416J
Policy No.	DMCVSNW00067462003	Coverage (\$)	0.00
Claim No.	SNM21D201759/C01/TANKL	Excess (\$)	500.00
Assign From	MERIMEN (TAN KAH LEONG)	Assign Date	09/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/03/2021	Inspection Date	09/04/2021
Survey held at	BLK K PANDAN LOOP IND #01-12		
Repairer	GOLDBELL ENGINEERING PTE LTD		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			