


GOLDBELL
ENGINEERING

 Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax : +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

(SUPPLEMENTARY)

 INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSNW00067462003	Date of Loss:	28/03/2021
Vehicle Reg. No.:	GBG6416J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TASTY FOOD CATERING PTE LTD	Contact No:	+6596968681
Driver:	VIJAYAKUMAR RAJARAM		

Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	19/09/2017
Vehicle Colour:	GREY		
Engine No:	1KD2648453	Chassis No:	KDH2010205346
Odometer:	173746 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	25

 Present Location: **GOLDBELL ENGINEERING PTE LTD (TUAS)**
COST OF CLAIMS

	Amount
Parts	1,061.60
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$)	1,061.60
-------------------------	-----------------

+ GST 7.00% (\$)	74.31
-------------------------	--------------

Nett Amount (\$)	1,135.91
-------------------------	-----------------

+ Previous Estimates (\$)	26,729.17
----------------------------------	------------------

Claim Total (\$)	27,865.08
-------------------------	------------------

 Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 01 Jun 2021)**Parts:** N/A TOYOTA HIACE 3.0 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/GBG6416J/01/06/2021 19:25**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*wiper tank	cra	0.00	0.00	*85.00 F
2	1		*support panel 1015	(change price)	0.00	0.00	*350.00 F
3	1		*wiper garnish 1311	cra	0.00	0.00	*500.00 F
4	1		*rr bumper centre clip 1007	nec	0.00	0.00	*12.60 F
5	1		*FRT DOOR GLASS OUTER MLDG 1661	nec	0.00	0.00	*57.00 F
6	1		*HOLDER CONNECTOR 1008	cut	0.00	0.00	*57.00 F

F=Franchise part.

Total Parts (\$\$) **1,061.60**

Goldbell Engineering Pte Ltd/GBG6416J/01/06/2021 19:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary:

FRT LWR CROSSMEMBER bent \$198.00
 L/LWR A-PILLAR REINFORCEMENT bent \$66.00
 L/LWR FRAME REINFORCEMENT bent \$96.00
 L/SUPPORT REINFORCEMENT bent \$162.00
 FAN HOUSING cracked \$132.00
 BONNET BUSH nec \$10.00
 LH FENDER MIRROR cracked \$93.00
 STEP GARNISH nec \$18.00
 BONNET STAY CLIP nec \$6.00
 FRT SUP/BRKT / LH bent \$54.00
 WIPER GARNISH COVER LH def \$18.00

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Goldbell Engineering Pte Ltd/GBG6416J/01/06/2021 19:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

