

14060



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

01/04/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SMV3370S

Veh Model :- TOYOTA VIOS 1.5

Estimate# :- CK421720

Claim # :-

ACC. Date :- 31/03/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPR	1 PC	537.10	537.10 ✓
2.	REAR BUMPER REINFORCEMENT	1 PC	397.80	397.80 X
3.	REAR BUMPER RETAINER RH & LH	2 PC	154.60	309.20 ✓
4.	REAR BUMPER CLIPS	10 PC	5.75	57.50 ✓
5.	REVERSE SENSOR	1 PC	288.10	288.10 ✓
6.	REAR END PANEL (REPAIR)	1 PC		
	LIST TOTAL S\$		1037.30	1,589.70
	25% DISCOUNT S\$		-259.33	-397.43
			777.97	1,192.27
LABOUR :				
	TO KNOCK AND STRAIGHTEN REAR END PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION			
	SPRAY PAINT REAR END PANEL, REAR BUMPER REINFORCEMENT, REAR BUMPER			
	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION			
	LABOUR TOTAL S\$		580.00	960.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,152.27

GST @ 7 % 150.66

AMOUNT DUE S\$ 2,302.93

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Tan Jiah 97495749
WP
c/s Remay after repair
Tan Jiah e/Handson