



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 8/4/2021

TO: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Our Customer : Soh Chin Heng
Vehicle No : SKZ9743M
Model : Hyundai Elantra
Manufacture Year : 2015
Date of Accident : 7/4/2021
Total Estimate Repair Days : 5
Total Pages : 1

Attn : Motor Claims Department
Fax: 6415 3727

Carlin

KMH4DH41CMG4655609.

Re: Repair Estimate For Third Party Claim against SMS7011T

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front fender RH <i>Dented</i>	1	\$753.00	\$753.00	<i>445</i>
2	Front fender mudflap RH <i>new</i>	1		\$0.00	<i>x</i>
3	Front fender inner shield RH <i>new</i>	1	\$92.00	\$92.00	<i>✓</i>
4	Front door RH <i>Dented</i>	1	\$1,157.00	\$1,157.00	<i>✓</i>
5	Front door hinge <i>new</i>	2		<i>65</i> \$0.00	<i>x</i>
6	Front door striker RH <i>new</i>	1		<i>58</i> \$0.00	<i>x</i>
7	Front door weatherstrip RH <i>new</i>	1		<i>198</i> \$0.00	<i>x</i>
8	Front door regulator RH <i>new</i>	1		<i>245</i> \$0.00	<i>x</i>
9	Front door regulator motor RH <i>new</i>	1		<i>308</i> \$0.00	<i>x</i>
10	Front door sash pillar black sticker RH <i>new</i>	1	\$45.00	\$45.00	<i>✓</i>
11	Rocker panel RH <i>new</i>	1	repair	repair	
	Sub-Total			\$2,047.00	<i>1739</i>
	Less 20%			\$409.40	
	Sub Total 1			\$1,637.60	<i>1391.20</i>
A.	Spare Parts (S/Nett)				
1	Front sports rim RH <i>new</i>	1	\$450.00	\$450.00	<i>+</i>
2	Front fender inner shield clip <i>new</i>	8	\$5.00	\$40.00	<i>30</i>
3				\$0.00	<i>20</i>
	Sub Total 2			\$490.00	
	Total for Parts			\$2,127.60	
B.	Labour				
1	To check wiring.			\$40.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	<i>300</i>
3	Spray painting all affected parts & areas.			\$800.00	<i>403</i>
4	To spray anti-rust undercoat.			\$30.00	<i>✓</i>
	Total Labour			\$1,270.00	<i>730</i>
	Total Repair Cost			\$3,397.60	



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	Adnan S.
Contact	96893733
Survey Date	09/04/21
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

04 Days

total: 2141.20

h/s: 1.7K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: