

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	▼	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS/CTI21004546/R1t3
3 ANSON ROAD #16-00		Date:	09/04/2021
SPRINGLEAF TOWERS SINGAPORE 079909		Code:	CTI
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBF 1282R
Policy No.	DMCVSNA00048312000	Coverage (\$)	0.00
Claim No.	SNM21D201852/C01/TOHHS	Excess (\$)	1,500.00
Assign From	MERIMEN (ALFRED TOH)	Assign Date	09/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/03/2021	Inspection Date	12/04/2021
Survey held at	53 Defu Lane 12, 539144 Defu Lan		
Repairer	YONG SING MOTOR WORKS		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			