

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Apr 2021)
 Parts: 143 MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHD6622A/12/04/2021 08:54
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,510.00 FL de -
2	1		*REAR BUMPER UNDER COVER	20.00	0.00	* 325 FL de ✓
3	2		*REAR BUMPER UNDER BRACKET RH/LH	20.00	0.00	*270.00 FL ? over ✓
4	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F 49 -
5	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*388.00 FA ✓

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 3,368.00
 - List Item Discount on L Items (S\$) 586.00

Total Parts (S\$) 2,782.00

ComfortDelGro Engineering Pte Ltd/SHD6622A/12/04/2021 08:54. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Supp Reinforcement - \$1150

3255
 20% - 2604
 SN - 438

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING - BOOTLID GARNISH ETC	New	600 800.00
2	SPRAY PAINTING - BOOTLID GARNISH ETC	New	500 800.00
3	R/I REVERSE SENSOR	New	30 120.00
Gross Labour Cost (S\$)			1130 1,720.00

ComfortDelGro Engineering Pte Ltd/SHD6622A/12/04/2021 08:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Giti 225/55R16

Tanpin 97495719

4138.

4573350
3 days

WP' 12/4/21 C 445

C/S Resurvey after repair

3 days

Tanpin C/Insurance

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Apr 2021)

Parts: 143 MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD6622A/15/04/2021 08:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	bt/*1,150.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,150.00
- List Item Discount on L Items (S\$)						230.00
Total Parts (S\$)						920.00

ComfortDelGro Engineering Pte Ltd/SHD6622A/15/04/2021 08:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS