Id	<	1	of 2 ?	>	Þ١	$\bigcirc$	<b>⊕</b>	100%	~		<sub>G</sub>	Find   Next	
----	---	---	--------	---	----	------------	----------	------	---	--	--------------	-------------	--



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts En	Automok	pi <b>l</b> e							
	ERGO INSURANC	E PTE LTD		Ref:	CS/EGI21004601/Kqf3							
	5 TEMASEK BOUL #04-05 SUNTEC T SINGAPORE 0389	OWER FIVE		Date:	12/04/2021							
				Code:	EGI							
1.	Policy Particulars :- THIRD PARTY CLAIM											
	Insured Veh.	GBB 9193H	Veh. Inspected		GBG 1925P							
	Policy No.		Coverage (\$)		0.00							
	Claim No. Cl	DMCG21000625-001	Excess (\$)		0.00							
	Assign From	ZHENG HAN YANG	Assign Date		12/04/2021							
2.	_	Vehicle Partie	culars & Condition	n								
	Make & Model		c.c		0							
	Engine No.	HIDDEN	Year of Reg.									
	Chassis No.		Colour									
	Odometer	-	Steering									
	Brakes		Modification									
	General											
3.		Conditi	ons of Tyres									
		Size	Make		Balance							
	R/H Front Tyre				mm							
	L/H Front Tyre				mm							
	R/H Rear Tyre				mm							
	L/H Rear Tyre				mm							
4.	Description of Damages											
5.	General Information											
	Accident Date	01/04/2021	Inspection Date	е	12/04/2021							
	Survey held at	BH AUTO SERVICES PTE LTD	<u> </u>									
		BLK 1 SIN MING INDUSTRIAL SECTOR C #01-115 SINGAPORE 575636	ESTATE									
5a.		R	emarks									
		ON WAS CONDUCTED ON A"WIT DE TO YOUR INSTRUCTIONS, W										