

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6766 Z

1 pc	Rear bumper	\$	696.00	104
1 pc	Rear bumper o/s side bracket	\$	16.00	?
1 pc	Rear o/s fender	\$	1,205.00	104
1 pc	Rear o/s fender inner shield	\$	120.00	X
1 pc	Rear windscreen moulding	\$	87.00	X
1 pc	Wheel cover	\$	116.00	cm
1 pc	Rear o/s shock absorber	\$	313.00	?
1 pc	Rear o/s lower arm	\$	351.00	?
1 pc	Rear o/s trailing arm	\$	159.00	X
1 pc	Rear o/s knuckle arm	\$	525.00	?
1 pc	Rear o/s hub bearing	\$	349.00	?
1 pc	Rear o/s Assist arm	\$	163.00	X
1 pc	Rear o/s rim	\$	246.00	R.?
		\$	4,346.00	
		Less 10%	\$	434.60
			\$	3,911.40

S/NETT

1 set	Rear bumper clips	\$	48.00	X
1 set	o/s door sticker	\$	100.00	60
1 pc	Rear o/s fender sticker	\$	60.00	30
1 set	Rear o/s fender inner shield clips	\$	28.00	X

12-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6766 Z

Sundry	\$	50.00 ²⁰
To dismantle / refit reverse sensor to new bumper and reset to the same	\$	120.00 ³⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ⁶⁰
To check wheel alignment	\$	80.00 ✓
To dismantle and replace rear o/s undercarriage	\$	180.00 ^{150 photo}
To dismantle and refit the rear windscreen	\$	120.00 X
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear o/s door etc	\$	1,000.00 ⁴⁰⁰
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish	\$	800.00 ⁷⁰⁰
To apply rustproofing on the repaired and replaced panels.	\$	150.00
	\$	<u>6,827.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*20% / 6766 Z
LKK*

*Tanfbin 97495749
in p' 22/4/21 R 530
L/S Resurvey after repair
3-4 days
Tanfbin @ Lkhartoon*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: