

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nadaraja, Deeban

Date: 13 Apr 2021

**Preliminary Advice**

Vehicle No	: SMT7845Z	Accident Date	: 17/03/2021
Make	: KIA STONIC	Policy No.	: 2070106817
Assignment Date	: 12/04/2021	Excess	: S\$300.00
Date of Inspection	: 12/04/2021	Est. Duration of Repair	: 3
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,778.00
Revised Amount	:S\$	1,249.60
Check Items (Estimated)	:S\$	40.80
Total	:S\$	1,290.40

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	37,123.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,877.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :