

INSURANCE CO. : AIG


Supplementary Parts For Registration No.: SMS 9674 S

<u>Parts</u>	<u>Cost (\$)</u>
1 Bumper Bracket <i>BT</i>	339.00 ✓
2 Air bulkhead LH <i>CRA</i>	137.00 ✓
3 Air bulkhead RH <i>CRA</i>	137.00 ✓
4 Front light LH <i>CRA</i>	642.00 ✓
5 Wdscrn Moulding RH <i>CUT</i>	289.00 ✓
6 Wdscrn moulding LH <i>CUT</i>	289.00 ✓
7 Drip Moulding RH <i>CUT</i>	58.00 ✓
8 Drip Moulding LH <i>CUT</i>	58.00 ✓
9 Condenser <i>bd</i>	1,165.00 ✓
10 Cooling liquid drum 3L PAE -35 (x2) <i>nec</i>	48.00 ✓
11 Rear duct <i>BR</i>	166.00 ✓
12 Front light RH <i>CRA</i>	642.00 ✓
13 Deflector <i>BR</i>	97.00 ✓

Total Labour	4,067.00
Less Discount 20%	813.40
Total after discount	3,253.60

<u>Labour</u>	<u>Cost (\$)</u>
1 Respray on both front fender apron	380.00 ✓
Total Labour	380.00
Taxable amount	3,633.60
7% GST	254.35
Grand total	\$ 3,887.95

Thank You.
Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240