

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TOPAIR ENGINEERING PTE LTD
 9002 TAMPINES ST 93 #04-62 TAMPINES IND
 PARK A
 SINGAPORE 528836

TP Budget Direct.
Veron

Contact : 98272858, 87311135

ESTIMATE

Repair Code : CLM16765
 Date in : 10/04/2021
 Vehicle Num. : GBF5319T
 Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V
 Chassis/Eng# : JN1MC2E26Z0006938/YD25403344A

Parts and Labour Assesment

| Description of part | Qty | Unit Price | Amount |
|--|-----|------------|------------|
| FRONT BUMPER <i>Distorted</i> | 1 | 541.70 | ✓ 541.70 |
| FRONT BUMPER LH FOGLAMP <i>cracked</i> | 1 | 320.70 | ✓ 320.70 |
| FRONT BUMPER LH FOGLAMP GARNISH <i>cracked</i> | 1 | 114.20 | ✓ 114.20 |
| FRONT BUMPER SIDE RETAINER L/R <i>LH cracked</i> | 2 | 155.60 | ✓ 311.20 |
| FRONT BUMPER TOW HOOK COVER <i>new</i> | 1 | 21.40 | + 21.40 |
| FRONT LH DOOR <i>Dented</i> | 1 | 1237.90 | ✓ 1,237.90 |
| FRONT LH DOOR CHECKER | 1 | 39.70 | + 39.70 |
| FRONT LH DOOR HINGE (LOWER) | 1 | 62.00 | + 62.00 |
| FRONT LH DOOR HINGE (TOP) | 1 | 62.00 | + 62.00 |
| FRONT LH DOOR WEATHER STRIP | 1 | 91.10 | + 91.10 |
| FRONT LH HEADLAMP <i>cracked</i> | 1 | 391.50 | ✓ 391.50 |
| FRONT LH LOWER ARM <i>Bent</i> | 1 | 228.20 | ✓ 228.20 |
| FRONT LH STABILIZER LINK <i>new one</i> | 1 | 59.00 | + 59.00 |
| FRONT LH STEP GARNISH <i>torn</i> | 1 | 65.00 | ✓ 65.00 |
| FRONT LH STEP PANEL <i>Dented</i> | 1 | 110.00 | ✓ 110.00 |
| FRONT LH TIE ROD END <i>New New</i> | 1 | 135.00 | + 135.00 |

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TOPAIR ENGINEERING PTE LTD
 9002 TAMPINES ST 93 #04-62 TAMPINES IND
 PARK A
 SINGAPORE 528836

Contact : 98272858, 87311135

ESTIMATE

Repair Code : CLM16765

Date in : 10/04/2021

Vehicle Num. : GBF5319T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0006938/YD25403344A

| | | Subtotal before discount | 3,790.60 |
|-----------------------------------|-------------|--------------------------|-------------------------------------|
| Percentage discount | 10% | 3320.40 | 379.06 |
| | | Sub-total 1 | 3,411.54 |
| FRONT BUMPER CLIPS - SET | <i>Nec</i> | 1 | 80.00 <i>30</i> 80.00 |
| FRONT LH DOOR BIZSAFE STICKER | <i>Nec</i> | 1 | 80.00 <i>40</i> 80.00 |
| FRONT LH DOOR COMPANY STICKER | <i>Nec</i> | 1 | 25.00 ✓ 25.00 |
| FRONT LH KNUCKLE ARM | <i>Demd</i> | 1 | 351.50 ✓ 351.50 |
| FRONT LH KNUCKLE ARM BEARING | <i>Demd</i> | 1 | 231.00 ✓ 231.00 |
| FRONT LH SHOCK ABSORBER | <i>Nec</i> | 1 | 160.20 ✗ 160.20 |
| FRONT LH STEP GARNISH CLIPS - SET | <i>Nec</i> | 1 | 25.00 ✓ 25.00 |
| FRONT LH TYRE | <i>Nec</i> | 1 | 380.00 ✗ 380.00 |
| FRONT LH WHEEL RIM | <i>Nec</i> | 1 | 500.00 <i>200</i> 500.00 |
| REAR LH DOOR STICKER | <i>Nec</i> | 1 | 400.00 <i>300</i> 400.00 |
| REAR LH FENDER STICKER | <i>Nec</i> | 1 | 400.00 <i>350</i> 400.00 |
| REAR LH TYRE | <i>Nec</i> | 1 | 380.00 ✗ 380.00 |
| REAR LH WHEEL BEARING | <i>Demd</i> | 1 | 91.30 ✓ 91.30 |
| REAR LH WHEEL BEARING SHAFT | <i>Nec</i> | 1 | 261.00 ✗ 261.00 |
| REAR LH WHEEL RIM | <i>Nec</i> | 1 | 500.00 <i>200</i> 500.00 |

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TOPAIR ENGINEERING PTE LTD
 9002 TAMPINES ST 93 #04-62 TAMPINES IND
 PARK A
 SINGAPORE 528836

Contact : 98272858, 87311135

ESTIMATE

Repair Code : CLM16765
 Date in : 10/04/2021
 Vehicle Num. : GBF5319T
 Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V
 Chassis/Eng# : JN1MC2E26Z0006938/YD25403344A

| | | |
|------------------------|--------------------------|-----------------|
| | Subtotal before discount | 3,865.00 |
| Percentage discount 0% | 1843.80 | 0.00 |
| | Sub-total 2 | 3,865.00 |
| | Parts-total | 7,276.54 |

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

30 80.00 ✓
 200 300.00 ✓
 80 300.00 ✓
 2150 80 100.00 ✓
 80 80.00 ✓
 1000 1,500.00 ✓
 700 1,000.00 ✓
 60 120.00 ✓

| | |
|---------------------------------|------------------|
| Labour Total | 3,480.00 |
| Parts & Labour Total | 10,756.54 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*** This is a computer-generated document which requires no signature.***
 page 3

Adrian S
 13/04/21 H/s.
 06 days.
 total: 6982.16
 H/s: 551C ✓