



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21004642/Utf3n2 Date: 22/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBR 3958Z	Veh. Inspected	SMR 1944X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101124/THE	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	13/04/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS J (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053HY9305143594	Colour	BEIGE
Odometer	148712 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	FIRENZA	6 mm
L/H Front Tyre	195/55 R15	FIRENZA	6 mm
R/H Rear Tyre	195/55 R15	FIRENZA	6 mm
L/H Rear Tyre	195/55 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/04/2021	Inspection Date	13/04/2021
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	