

Hui Zhen (LKK Auto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 June 2021 12:39 pm
To: Hui Zhen (LKK Auto)
Subject: FW: SLW 4098D DATE OF ACCIDENT : 11/04/21

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto)
Sent: Friday, 11 June 2021 12:30 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SLW 4098D DATE OF ACCIDENT : 11/04/21

Case Finalised

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Daniel T [<mailto:enquiry@afcars.com.sg>]
Sent: Friday, 11 June, 2021 11:56 AM
To: Rasul (LKKAuto)
Subject: Re: SLW 4098D DATE OF ACCIDENT : 11/04/21

Hi Rasul,

Noted with thanks.

Confirmed.

Sent from my iPhone

On 9 Jun 2021, at 12:20 PM, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Brandon,

Refer to attachment

Some of the parts prices required audit check. Need to be adjusted.

The Finalised amount is \$ 5,500 / 7 days of lump sum repair

Kindly reply on acceptance

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<image001.jpg>

Save the Earth. Print only when necessary.

<SLW 4098D.pdf>