



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: DAVID PHUA

Ref: CS/INC21004689/Aqf3n2

Date: 07/06/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8618E	Veh. Inspected	SKS 9375D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1127870-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	13/04/2021

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180K	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2040452A263603	Colour	GREY
Odometer	174545 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	6 mm
L/H Front Tyre	225/45 R17	MICHELIN	6 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/04/2021	Inspect Date / Time	13/04/2021 ( 11:33 AM )
Survey held at	SMARTONE AUTO PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**