

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC-4S
LKK-

Date: 09.04.2021

Time: 10:11:08

Page: 1/3

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305462896
 REGN NO : SHA6603X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 08.04.2021 11:00
 ACCIDENT DATE : 08.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	REAR NO.PLATE W/TRIM CVR	1 N	55.00	10.00	49.50	cur ✓
0002 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	de ✓
0003 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	de ✓
0004 04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	X ny ✓
0005 04-01-0104-2540-G	REAR BUMPER UNDER CTR CVR	1	255.00	20.00	204.00	X ny ✓
0006 04-01-0104-2370-G	REAR BUMPER FOG LAMP	1	201.50	20.00	161.20	arb ✓
0007 04-01-0104-0852-G	REAR BUMPER REFLECTOR RH	1	41.45	20.00	33.16	X ny ✓
0008 04-01-0104-0851-G	REAR BUMPER REFLECTOR LH	1	41.45	20.00	33.16	X ny ✓
0009 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	na ✓
0010 09-01-0104-2133-G	SMART KEY ANTENNA	1	40.50	20.00	32.40	? cur ✓
0011 04-01-0104-2288-G	REAR BUMPER BEAM	1	394.80	20.00	315.84	cur ✓
0012 04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48	X ny ✓
0013 04-01-0104-3819-G	REAR BUMPER STAY LH	1	138.10	20.00	110.48	? ht ✓

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC-45
LKK-

Date: 09.04.2021

Time: 10:11:08

Page: 2/3 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305462896
 REGN NO : SHA6603X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 08.04.2021 11:0
 ACCIDENT DATE : 08.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2544-G	REAR BUMPER TOW COVER	1	98.80	20.00	79.04	X n7	1707.55
0015 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00	m ✓	20% 1366.04
0016 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	ne ✓	N-235 10% 211.50
SUB-TOTAL : 2,211.38							8N-50. 1627.54

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	R/I REVERSE SENSOR	120.00	80.
0003 L	Diagnose/Reset SmartKey to Specs.	300.00	?/150 report Run.
0004 23-01	TOWING FEE	0.00	X n7 630.

SUB-TOTAL : 1,120.00

2257.54
 2/3 \$1800
 2 days.