



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YU DOMINIC YISHAN			Ref: CS/ASM21004692/T1vce2 Date: 03/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4071M	Veh. Inspected	SLZ 4401X	
Policy No.		Coverage (\$)	0.00	
Claim No.	S1M037TZ	Excess (\$)	0.00	
Assign From	YU DOMINIC YISHAN	Assign Date	13/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A200	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD1760432J454235	Colour	GREEN	
Odometer	54237 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35 R19	PIRELLI	6 mm	
L/H Front Tyre	235/35 R19	PIRELLI	6 mm	
R/H Rear Tyre	235/35 R19	PIRELLI	6 mm	
L/H Rear Tyre	235/35 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2021	Inspection Date	14/04/2021	
Survey held at	25 KAKI BUKIT ROAD 4 SYNERGY@KB #01-44			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	