

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408686

TEL 6396 2323 FAX 6641 1183

E-MAIL: NOPIA.KHAZ@PREMIUMALTO.COM.SG CLAIMS@PREMIUMALTO.COM.SG

ESTIMATE	ACCIDENT REPAIRS
WORKSHOP	UBI ROAD 1
CONTACT NO	6396 2323
FAX NO	6641 1183
REFERENCE	PA/TP0320/202144R
DATE	14-Apr-21
WIP	23240

VEHICLE NOT IN WORKSHOP KINDLY ARRANGE FOR SURVEY ON 16/4/21
YOUR INSURED VEH NO SMT 907 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY 1

#07-01 AIG BUILDING

SINGAPORE 079121

Auto Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4628

OWNER'S NAME
ADDRESS

MIS MURVASLINDA BTE RAMLI
BLK 56 CHAI CHEE DRIVE
#11-154

TELEPHONE

SINGAPORE 480066

HP +6561000469

TYPE OF CLAIM

THIRD PARTY CLAIM

POLICY NO

1800143831-01

VEHICLE NO

SEA 8890 U

MODEL CODE

Q5 SPORT 2.0 TFSI

MODEL YEAR

30/11/2018

ENGINE NO

DAX 040620

CHASSIS NO

WALUZZZFY7J2238968

MILEAGE

DATE IN

JOHNNY BOO / ALLAN WU

ESTIMATED BY

13-Apr-21

ACCIDENT DATE

NEAR ALONG PIE

PLACE OF ACCIDENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDX 6690 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,200.00	600 550 500.00
3	TO REPSRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,800.00	400 2050 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,552.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDX 6690 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - TOP X <i>Repair</i>	1	\$ 1,907.00	
2	REAR BUMPER - BOTTOM <i>for</i>	1	\$ 1,196.00	956.80
3	REAR BUMPER SPOILER <i>for</i>	1	\$ 866.00	692.80
4	REAR BUMPER CLOSING ELEMENT - LH / RH ? X NN	2	\$ 192.00	
5	REAR BUMPER CHROME TRIM - LH / RH X NN	2	\$ 474.00	
6	TAIL LIGHT - LH / RH X NN	2	\$ 1,398.00	
7	REAR BOOT LID CONTROL UNIT X NN	1	\$ 411.00	
8	REAR BUMPER CARRIER ? X NN	1	\$ 981.00	
9	REAR BUMPER SEAL ? X NN	2	\$ 6.00	
10	REAR BUMPER HOLDING STRAP X NN	1	\$ 168.00	
11	REAR PARKING AID SENSOR X NN	2	\$ 488.00	
12	REAR PARKING AID SENSOR SEAL RING X NN	4	\$ 14.00	
13	3MM ADHESIVE <i>for</i>	1	\$ 19.00	14.88
14	'AUDI' EMBLEM <i>for</i>	1	\$ 138.00	110.00
15	'Q5' EMBLEM <i>for</i>	1	\$ 99.00	79.04
16	'QUATTRO EMBLEM' <i>for</i>	1	\$ 99.00	79.04
17	'TFSI' EMBLEM <i>for</i>	1	\$ 99.00	79.04
18	REAR WHEEL ARCH COVER - LH / RH <i>for</i>	2	\$ 1,166.00	932.80
19	SUNDRIES ? X NN	1	\$ 200.00	
TOTAL SPARE PARTS		:	\$ 9,921.00	
TOTAL LABOUR CHARGES		:	\$ 5,552.00	
GRAND TOTAL		:	\$ 15,473.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Aug Qian - 8288 0282
4 Days
before paint photos.
16/4/2021.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT