

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	▼	🖨		Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	----------------------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD		Ref:	CS/SMR21004707/Buf3
60 WOODLANDS INDUSTRIAL PARK		Date:	14/04/2021
E4SINGAPORE 757705		Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 5139X	Veh. Inspected	SLK 1186R
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/04/21/2026	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	14/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/04/2021	Inspection Date	14/04/2021
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			