

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE  
 50 BUKIT BATOK STREET 23  
 #02-02 MIDVIEW BUILDING  
 SINGAPORE 659578  
 TEL: 68966619 FAX: 62678616

BIKE NO: JSH1804

S/N	DESCRIPTION/ MATERAIL	Quotation
1	COVER SET <i>scr</i>	\$ 350.00
2	RIM (F&R) <i>repair (L 30)</i>	\$ 350.00 <i>XR</i>
3	MIRROR <i>scr</i>	\$ 30.00
4	HANDLE BAR <i>bt</i>	\$ 75.00
5	FOOTREST <i>bt</i>	\$ 250.00
6	HEADLIGHT <i>scr</i>	\$ 85.00
7	LEVER <i>X</i>	\$ 25.00 <i>X</i>
8	FORK (FRONT) <i>bt</i>	\$ 220.00
9	FOOTREST PEDAL <i>X</i>	\$ 75.00 <i>X</i>
10	FOOTREST BRACKET (REAR) <i>bt</i>	\$ 55.00
11	GEAR LEVER <i>bt</i>	\$ 45.00
12	UNDER BRACKET <i>bt</i>	\$ 220.00
13	STEERING CONE <i>scr</i>	\$ 85.00
14	METER <i>scr</i>	\$ 240.00
TOTAL		\$ 2,105.00
(LESS 10% DISCOUNT)		-\$ 210.50
		\$ 1,894.50
PLUS 7% GST		\$ 132.62
		\$ 2,027.12
Add special nett items from above		
15	TOWING FEE	\$ 40 <del>50.00</del> <i>receipt?</i>
16	NO. PLATE <i>scr</i>	\$ 10 <del>25.00</del>
17	ALIGN BODY	\$ 100 <del>200.00</del>
18	LABOUR CHARGES	\$ 200 <del>350.00</del>
<b>Lump sum repair adjustment</b>		\$ 2,635.00

*1655*  
*10%*  
*1489.50*

*350* { \$ 40 ~~50.00~~ *receipt?*  
 \$ 10 ~~25.00~~  
 \$ 100 ~~200.00~~  
 \$ 200 ~~350.00~~

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*1489.50*  
*350.00*  
*1839.50*  
*20%*  
*1471.60*  
*45-1450*  
*3 days*

*RASUL*  
*Hp 90010068*  
*3 days*  
*4/5*  
*14/04/21 @ 1510*  
*Resuy after repair*