

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	▼	🖨		Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	----------------------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS/CTI21004721/Btf3		
3 ANSON ROAD #16-00		Date: 14/04/2021		
SPRINGLEAF TOWERS SINGAPORE 079909		Code: CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9930B	Veh. Inspected	SLT 9652L	
Policy No.	DMCVSNW00122572000	Coverage (\$)	0.00	
Claim No.	SNM21D202065/C02/TANKL	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY HUI PING)	Assign Date	14/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/04/2021	Inspection Date	14/04/2021	
Survey held at	LYE DESIGNS 10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				