

RS AUTO SERVICES

UEN No. 53428926E
160 Sin Ming Drive, #06-01
Sin Ming Auto City, Singapore 575722
Email: rsautoservices88@gmail.com

Date : 15/03/2021

QUOTATION -THIRD PARTY CLAIM SUPPLEMENTARY

SOMPO INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 13/04/2021

Claim : Third Party Claim
Veh. No : SLA 8836 E
Model : NISSAN TEANA
Insured Ins: NTUC INCOME

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : GBD 1065 L		
1	FLOOR PANEL LOWER COVER	\$ <i>Per</i> 480.00	X
1	SPARE TYRE TOP CENTER SPONGE <i>175.80 C.M.</i>	\$ 420.30	✓
1	SPARE TYRE PANEL LH SPONGE <i>Replaced</i>	\$ 385.00	X
1	SPARE TYRE PANEL RH TOOL TRAY	\$ 399.60	X
2	REAR BUMPER REINFORCEMENT BRACKETS <i>073.80 R</i>	\$ 280.00	✓
<i>2</i>	REAR BUMPER SENSORS <i>Double</i>	\$ 940.00	<i>2</i> X Repeated
4	REAR BUMPER SENSOR OUTER RIMS <i>Per</i>	\$ 392.00	X
4	REAR BUMPER SENSOR RUBBER SEALS <i>na</i>	\$ 232.00	X
1SET	REAR BUMPER SENSOR CABLE <i>Per</i>	\$ 268.00	X
2	REAR CHASSIS	REPAIR	
		\$ 3,796.90	
	Less 10%	\$ 759.38	
		\$ 3,037.52	
	TOTAL PARTS :	\$ 3,037.52	