



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KHOR SAW THENG

Ref: CC4/ASM21004749/Apa3q2
Date: 13/09/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6751C	Veh. Inspected	SMU 4079H
Policy No.	GA554592/1	Coverage (\$)	0.00
Claim No.	S1M0380L	Excess (\$)	0.00
Assign From		Assign Date	14/04/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2040492A404036	Colour	BLACK
Odometer	135913 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	6 mm
L/H Front Tyre	225/45 R17	MICHELIN	6 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2021	Inspection Date	14/04/2021
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**