CC 4/ ASM21004768/4693 ASS. REC. BY: MCVCL SLZ 8371/ Yr Regn: 21/5/18 Veh No: Date: From: Estimated Cost: Truck / Trailer or 4 ITP) WS ITP RES / OD RES / EVA / INV / MV 52283714 c.c /3/7 Make: Insured / Std / NI / NA at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading of SMH 67905 Eng/No: Insured: GK31316647 C/No: Policy No. Claims No. Steering: Inorder Jammed / Leaked / Burnt or Sum Insured: Excess: Jaorder / Jammed / Leaked / Burnt or Brake: (Client's Record) Nil S/Rim / STD A/Rim or Make of Veh: 175-170214 Tyre Size: (Policy Condition) N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Front Bal. or Market Value: R/Bal. mm IDAC Accident Rport: Consistent?: Yes or No L/Bal. Consistent?: Yes or No GIA / PR Seen: D.O.A. Res.: Yes or No Est. Repairs: days 3 Val.: Yes or No Survey held at Lum Sum: 994C Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date: De7812 Date / Time Action / Instruction 21A & 30717 have his 5/8/M 2/5 \$ 5300 confirmed with Alen. Date/Time, File Pass to? : Preli. Report Days Of Repair: Resurvey No. of Trip: Survey Fee:

sportation:
S + RS,SI
otos
ners
OTAL
5

	Kel	i Josev	Not	Albert
v				Alah
	FASTECH AUTO PTE LTD		10	111/1
	BLK 1 KAKI BUKIT AVE 6		/2	1414
	#01-48 AUTOBAY		1/	, (300)
	SINGAPORE 417883		2/5_	\$
			1 1ch	-she Ather as
VEHICLE N	o:SLZ 8371Y		000	6days
1PC	REAR WINDSRCEEN		11	\$1,422.30 X
1PC	REAR WINDSCREEN MOULDING		nu "	\$68.10
1PC	TAILGATE 749.60		solim?	\$845.20
1PC	TAILGATE OUTER GARNISH		11	\$355.40 X
1PC	TAILGATE 'H' LOGO		11	\$35.00
1PC	TAILGATE 'FIT' EMBLEM		ner	\$38.00
1PC	TAILGATE REAR WIPER MOTOR		11	\$485.20 X
2PCS	TAILGATE LICENCE PLATE LAMPS @\$85.00		11	\$170.00 ×
2PCS	TAILGATE REFLECTORS @\$281.00		17	\$562.00 X
1PC	TAILGATE INNER LOCK /97	40	1,00	\$209.20
1PC	TAILGATE INNER TRIM BOARD 281.	20	De/Cre	\$388.20
1SET	TAILGATE INNER TRIM BOARD CLIPS		nu	\$30.00
1PC	TAILGATE INNER PULL GARNISH		11	\$35.00 🗶
1PC	TAILGATE WEATHERSTRIP		101	\$166.80
1PC	REAR BUMPER	492-20	De	\$645.50
1PC	REAR BUMPER LOWER CENTRE BLACK GARNISH	1	suff nec	\$115.00
2PCS	REAR BUMPER LOWER SIDE GARNISHS @\$65.0	0	11	\$130.00 ×
2PCS	REAR BUMPER SIDE RETAINERS @\$22.50		nu	\$45.00
1SET	REAR BUMPER CLIPS		nu	
1PC	REAR BUZZLE SENSOR		11	\$350.00
1PC	REAR ANTENNA SENSOR	/ .	11	\$320.00 2
2PCS	TAILLAMPS @\$450.20 288-WXZ.	= \$76.40	cha	\$900.40
2PCS	TAILLAMP HOUSING PANELS @\$425.00		2010.1	\$850.00 X
1PC	REAR END PANEL 32 8.	60	DO/Bent	
1PC	REAR END PANEL TOP GARNISH		101	\$198.00
1PC	REAR FLOOR PANEL		2	\$945.20 🗙
1PC	REAR FLOOR PANEL TOP BOARD 3/6 REAR FLOOR TOOLS SPONGE 465. 20		Magis	\$365.00
1PC	MEANN'I EGON TOOLS STONGE		No. of the last of	1,942.00
2PCS	REAR FENDERS @\$971.00 REAR FENDER INNER TRIMS @\$365.00 2 62-3	2- 2	Deltura	\$730.00
2PCS 1SET	REAR FENDER INNER TRIM CLIPS	10 × 67 20 4.60		\$30.00
1PC	REAR EXHAUST		17	\$645.00 🗶
1PC	REAR EXHAUST HEAT SHIELD	1	11	\$185.00 ×
1PC	REAR EXHAUST MOUNTING	20-/	12	\$35.00 ×
1PC	CENTRE EXHAUST PIPE	(do	11	\$942.30 /
2PCS	REAR AIR VENTS @\$35.00		11	\$70.00 7
2PCS	REAR FLOOR INNER SIDE PANELS @\$188.00		R	\$376.00 🗡
2103	REAR FEOOR INVERSIBLE FARELS @\$150.00			15,705.80
	S.NETT			
1PC				\$280.00 🔀
1PC	REAR WINDSCREEN SOLAR FILM REAR WINDSCREEN SEALANT **A Comparison of the comparison			\$50.00 40

1PC 1PC 1SET 1SET 1PC 1PC 1SET	REAR WINDSCREEN INNER SEAL REAR LICENCE PLATE W/HOLDER REAR REVERSE CAMERA REAR BUMPER REVERSE SENSOR REAR FENDER GLASS SEALANT REAR END PANEL SEALANT REAR FLOOR PANEL INSULATOR	\$30.00 \(\) \$50.00 \(\times \) \$380.00 \(\times \) \$250.00 \(\times \) \$80.00 \(\times \) \$50.00 \(\times \) \$280.00 \(\times \)
	TO CHECK WIRING TO DISMANTLE & REPLACED REVERSE SENSOR TO DISMANTLE & REFIX REAR WINDSCREEN TO DISMANTLE & REFIX CUSHION UPHOLSTERY TO DISMANTLE & REPLACED REAR EXHAUST TO DISMANTLE & REFIX FUEL TANK TO DISMANTLE & REFIX REAR UNDER CARRIAGE TO CONDUCT WHEEL ALIGNMENT TO DISMANTLE & REFIX REAR FENDER GLASS LH/RH TO MOUNT VEHICLE ON CAR O-LINER TO TRANSFER TAILGATE MECHANISM TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & REPLACED PARTS TO PUTTY & SPRAY PAINTING	\$80.00 30 \$80.00 SD \$150.00 LDO \$150.00 X \$150.00 X \$150.00 X \$120.00 X \$120.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X \$150.00 X
		TOTAL \$25.405.80

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "V! ithout Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

202 9-3754.2f 5.N-460 1-2420 6634.08 5:307

\$25,495.80

TOTAL