

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7147Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER BRACKET TOP RH	DEFORMED	44.80	44.80
1	FRT FENDER RH	BENT	663.00	663.00
1	FRT FENDER SHIELD RH	TORN	174.90	174.90
1	HEADLAMP RH	CRACKED	1,800.00	1,800.00
1	HEADLAMP SUPPORT PANEL	NOT AVAILABLE	907.40	-
1	FRT BONNET	TO REPAIR SEE LABOUR	2,265.90	-
2	BONNET HINGE LH RH @\$126.70	TO REPAIR SEE LABOUR	253.40	-
1	FRT WINDSCREEN PILLAR OUTER RH	TO REPAIR SEE LABOUR	1,745.50	-
1	FRT DOOR RH	NOT NECESSARY	2,256.40	-
1	FRT WHEEL HUB CAP RH	CRACKED	217.20	217.20
	LESS 25% DISCOUNT		-2,850.68	-993.53
			8,552.02	2,980.57
	SPECIAL NETT ITEMS			
1	FRT FENDER ADVERTISEMENT LOGO (SN)	CUT	100.00	100.00
1	FRT DOOR COMFORT LOGO LH (SN)	NOT NECESSARY	75.00	-
			175.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRT BONNET ,BONNET HINGE LH RH AND FRT WINDSCREEN PILLAR OUTER RH .		1,200.00	560.00
	SPRAY PAINTING CHARGE.		1,250.00	850.00
	TRANSFER OF DOOR .	NOT NECESSARY	120.00	-
	TUFF KOTE.		60.00	30.00
	WIRING CHARGE.		60.00	30.00
			2,690.00	1,470.00
	GRAND TOTAL		11,417.02	4,550.57

Report Ref No. CC3/QW21004769/T1rs3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,650.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/QW21004769/T1rs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

X:2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.