

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBJ 5947J  
TP/AIG

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120  
 TEL: 64193000 FAX: 64153727  
 ATTN: Motor Claim Department

**Estimate No:** ES2190361/YISHUN  
**Date:** 15 Apr 2021  
**Policy No:** DMCVSNW00041852001  
**Veh Reg No:** GBJ5947J  
**Make/Model:** NISSAN NISSAN NV200  
 DX 1.6 AUTO  
**Chassis No:** VM20133727  
**Engine No:** HR16143782D  
**Reg. Date:** 12/06/2019

WS Ref: TP/AIG  
 Claim Type: Third Party  
 Accident Date: 14/04/2021  
 TP Veh Reg No: SCM8898U

NOT NOTICED  
 REPAIR BY PAINT  
 6 days

## Estimate Repair Cost to Vehicle No :GBJ5947J

PAGE: 1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
<b>Net Price</b>				
1 REAR BUMPER	485.90	1 PC	485.90 ✓	
2 REAR BUMPER SPONGE	94.00	1 PC	94.00 ✗	
3 REAR BUMPER CLIPS	4.50	6 PCS	27.00 ✓	
4 REAR TAILGATE	1,978.40	1 PC	1,978.40 ✓	
5 TAILGATE LOGO	69.70	1 PC	69.70 ✓	
6 TAILGATE EMBLEM (NV200)	87.60	1 PC	87.60 ✓	
7 TAILGATE EMBLEM (VANETTE)	69.70	1 PC	69.70 ✓	
8 TAILGATE INNER LOCK	281.10	1 PC	281.10 ✓	
9 REAR TAILGATE RUBBER	96.40	1 PC	96.40 ✓	
10 REAR END PANEL INNER TOP GARNISH CLIPS	5.00	5 PC	25.00 ✓	
			3,214.80	
REG reverse sensor shot 200-cosm ✓			Less 10%	321.48
			2,893.32	
<b>Special Net</b>				
11 REAR END PANEL OUTER	162.40	1 PC	162.40 ✗	
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00 ✓	
13 STICKER - 5 PAX	10.00	1 PC	10.00 ✓	
14 STICKER - 70 KM/H	10.00	1 PC	10.00 ✓	
15 STICKER - 600 KG	28.00	1 PC	28.00 ✓	
			250.40	250.40
<b>Labour</b>				
16 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00 ✓	
17 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, INNER LOCK, GARNISH, REAR FLOOR BOARD, CARPET, CUT, WELD & RENEW REAR END PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL & REALIGN THE SAME	800.00	1 LA	800.00 ✓	
18 PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL, REAR END PANEL, TAILGATE & ALL REAR AFFECTED AREAS	900.00	1 LA	900.00 ✓	
19 RUSTPROOFING	60.00	1 LA	60.00 ✓	
20 TO REWRITE ADVERTISEMENT	280.00	1 LA	280.00 ✓	
			2,160.00	2,160.00

Total S\$ 5,303.72  
 Add GST @ 7% 371.26  
**Total Amount Payable S\$ 5,674.98**

**For Cheng Hoe Motor Pte Ltd**

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_