

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBJ5947J
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2190361/YISHUN
 Date: 15 Apr 2021
 Policy No: DMCVSNW00041852001
 Veh Reg No: GBJ5947J
 Make/Model: NISSAN NISSAN NV200
 DX 1.6 AUTO
 Chassis No: VM20133727
 Engine No: HR16143782D
 Reg. Date: 12/06/2019

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 14/04/2021
 TP Veh Reg No: SCM8898U

NOT Notified
Running Bk paint
6 days

Estimate Repair Cost to Vehicle No :GBJ5947J

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	485.90	1 PC	485.90	
2 REAR BUMPER SPONGE	94.00	1 PC	94.00	
3 REAR BUMPER CLIPS	4.50	6 PCS	27.00	
4 REAR TAILGATE	1,978.40	1 PC	1,978.40	
5 TAILGATE LOGO	69.70	1 PC	69.70	
6 TAILGATE EMBLEM (NV200)	87.60	1 PC	87.60	
7 TAILGATE EMBLEM (VANETTE)	69.70	1 PC	69.70	
8 TAILGATE INNER LOCK	281.10	1 PC	281.10	
9 REAR TAILGATE RUBBER	96.40	1 PC	96.40	
10 REAR END PANEL INNER TOP GARNISH CLIPS	5.00	5 PC	25.00	
			3,214.80	
		Less 10%	321.48	2,893.32
Special Net				
11 REAR END PANEL OUTER	162.40	1 PC	162.40	
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	
13 STICKER - 5 PAX	10.00	1 PC	10.00	
14 STICKER - 70 KM/H	10.00	1 PC	10.00	
15 STICKER - 600 KG	28.00	1 PC	28.00	
			250.40	250.40
Labour				
16 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
17 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, INNER LOCK, GARNISH, REAR FLOOR BOARD, CARPET, CUT, WELD & RENEW REAR END PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL & REALIGN THE SAME	800.00	1 LA	800.00	
18 PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL, REAR END PANEL, TAILGATE & ALL REAR AFFECTED AREAS	900.00	1 LA	900.00	
19 RUSTPROOFING	60.00	1 LA	60.00	
20 TO REWRITE ADVERTISEMENT	280.00	1 LA	280.00	
			2,160.00	2,160.00

Total S\$ 5,303.72
 Add GST @ 7% 371.26
 Total Amount Payable S\$ 5,674.98

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: