

Our Job Ref No : 305463170  
Date : 20/04/21

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK  
Attn : TAUFIKH  
Vehicle Reg No. : SHC1884Z

Fax :

09/04/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC SKL7873H

2. The finalized amount shall be:


(a) Spare Parts after List discount	<u>\$1,198.15</u>
(b) Labour Charges	<u>\$880.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<u><b>\$2,078.15</b></u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
<b>Final Lumpsum Repair cost</b>	

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature : taufikh  
Name : Taufikh  
Date : 20/5/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305463170  
 REGN NO : SHC1884Z  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4A)  
 DATE OF REGN : 04.08.2020  
 DATE/TIME IN : 10.04.2021 09:40  
 ACCIDENT DATE : 09.04.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2712-G	COVER REAR BUMPER	1	458.60	25.00	343.95
0002 04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1	552.60	25.00	414.45
0003 04-01-0302-2715-G	COVER RR BUMPER -TOW HOOK	1	82.70	25.00	62.02
0004 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0005 09-01-0302-2005-A	REVERSE SENSOR ASSY	1	135.70	10.00	122.13
0006 04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1	318.80	25.00	239.10

SUB-TOTAL : 1,198.15

## JOB NATURE

0000 PB	PANEL BEATING	350.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 880.00