## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Make

Model

Vehicle No. : SHD7130X

DOA: 09.04.2021

: HYUNDAI

:1-40

Date: 12/04/21

Insurance: NTUC

MVA: MS. LOKE YY

rascoulers s	Parts Description / Labour		Туре	Unit Price	Amount
SALES CONTRACTOR	FRONT BUMPER COVER	The state of the s			\$1,052.20
	FRONT BUMPER CLIPS			\$2.20	\$22.00
	1 FRT BUMPER GRILLE LH				\$187.20
	1 FRT BUMPER BRACKET TOP LH				\$187.20 \$44.80
	1 HEADLAMP LH				\$1,800.00
	1 RADIATOR GRILLE U MOULDING				\$94.70
	TRADIATOR GRIELE O MODEDING	SUB TOTAL			\$3,200.90
		LESS 20%			\$640.18
		DISCOUNTED TOTAL			\$2,560.72
	ii	DIOGGONIED TOTAL			
	Labour Charac				\$-
	Labour Charge PANEL BEATING				- 4
	SPRAY PAINTING CHARGE				\$350.00
122	WIRING CHARGE				\$300.00
	WIRING CHARGE	70741 1 422 2112			\$60.00
F 18	the state of the s	TOTAL LABOUR			\$710.00
		ESTIMATE TOTAL			\$350.00 \$300.00 \$60.00 \$710.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Touth 9749749 WR 1 1314/218 12pm 2 days Us resum after year

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subje : to confirmation
- Third party survey is on a "Without Prejudice" basis

1/59/600 Vdup.

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Compa-

Page 1