

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	✓	🖨		Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	--	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CS/CTI21004806/Eqf3 Date: 16/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8369P	Veh. Inspected	PZ 6	
Policy No.	DMCVSNW00048542000	Coverage (\$)	0.00	
Claim No.	SNM21D202152/C02/TOHHS	Excess (\$)	0.00	
Assign From	MERIMEN (ALFRED TOH)	Assign Date	16/04/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/04/2021	Inspection Date	22/04/2021	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				