



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004813/Ktf3e2	
			Date: 06/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBB 967B	Veh. Inspected	SMK 522Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101151/RUC	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	16/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES A180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD1760422J757154	Colour	RED	
Odometer	52945 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	8 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	8 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	8 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2021	Inspection Date	19/04/2021	
Survey held at	STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE, #04-05, SIN MING AUTOCARE, SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	