

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sq

GST No: 201700521W UEN No: 201700521W

MEL 2021 D 000/1/80

Our Ref

SMQ4697U

Yours Ref

SLL7627R

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-05 IOB BUILDING SINGAPORE 049711

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SMQ4697U & SLL7627R ON 11/04/2021 @ 11:20 HRS ALONG

TPE TURNING INTO CTE

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair

S\$4,059.58

Loss of Use (\$ 150.00 x 3 days)

S\$450.00

Additional Loss of Use (\$ 150.00 x 1 days) - Weekend

S\$150.00

GIA / LTA Search

S\$7.45

S\$4,667.03

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE TO

04 May 2021

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08

WESTGATE TOWER SINGAPORE 608531, owner of SMQ4697U hereby authorize TONG

LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or
rental and/or loss of use for our vehicle no.: SMQ4697U that was damaged pursuant to the
accident which occurred on 11/04/2021 ALONG TPE TURNING INTO CTE involving vehicle
nos: SLL7627R

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 15th day of April 2021

ken

Signed by third party claimant

TONG LUCK AUTO PTE LTD



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711

Office (65) 63476100 Email insure@iii.com.sg Fax (65) 62244174 Website www.iii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref:MFL2021D0001680 Claimant Ref:SMQ 4697U

We/I, Tong Luck Auto Pie Lid ("the workshop") here	eby confirm that we/I have reached an agreement				
with the appointed Surveyor of India International Insurance Pte Ltd	LKK Auto Consultants Pte Ltd (name				
of Surveyor) with respect to the amount claimed for S\$ $4,059.58$	(repair cost), S\$ 600.00 (loss of				
use/rental), S\$ 7.45 (search fee), vehicle no.SMQ 4697U that was of					
on 11/04/2021 (date) at TPE TURNING INTO CTE (location) involving vehicle no. SLL 7627R (insured					
vehicle). This is pursuant to the inspection conducted on 16/04/2021 (date	A COLOR SECTION OF THE PROPERTY OF THE PROPERT				
(auto	, at the memory				
We/I confirm that we/I are/am authorized by the owner DAIMLER FLEET MA claimant") of vehicle noSMQ 4697U to make the claim as set out in the above the matter on his/her behalf in a manner that we/I deem fit. We/I encloparty claimant".	bove paragraph and we/I have full authority to settle				
We/I further confirm that we/I will indemnify India International Insurance	e Pte Ltd for all damages, loss and/or expense that				
they will or have already incurred in the event that "the third party cla	aimant" after the above said agreement lodges a				
further claim against the former for any loss and expenses suffered per					
of use pursuant to the damage to SMQ 4697U (vehicle no.) as a result of					
We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.					
This agreement is subject to the application of Singapore law and the Sir	ngapore Courts have exclusive jurisdiction over any				
dispute arising out of the same.					
We/l authorize you to pay the total amount of S\$_4,667.03_to_Tong	g Luck Auto Pte Ltd				
Dated this 10 day of August 2021					
CLAIMANT:	WITNESS: ((LKK))				
	KSC				
Signature: Signed by "the workshop" (with chop)	Signature: Signed by appointed Surveyor	_			
Signed by the watershop (with chop)	LIKIK Anda Camanillanda Phallad				
Name:	Name: LKK Auto Consultants Pte Ltd	_			
NRIC:	NRIC: 199607198R				
TONG LUCK AUTO PTE LTD	Address 51 Uhi Avenus 4				
Address: 160 Sin Ming Drive #07-01/06	Address: 51 Ubi Avenue 1	-			
Sin Ming AutoCity	#01-25 Paya Ubi Ind. Park S(40893	3)			
Singapore 575722	NI-K				
Nationality: Tel: 6250-0088 Fax: 6250-5545	Nationality:	-			
Occupation:	Occupation:	_			

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Website: www.tlauto.com.sg

Email: operation@tlauto.com.sg UEN: 201700521W GST NO.: 201700521W

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-02

IOB BUILDING

SINGAPORE 049711

ATTN: MOTOR CLAIMS DEPT

TEL: 6849 8118

FAX:

YOUR REF NO : SLL7627R

CLAIM TYPE

: THIRD PARTY

ACCIDENT DATE : 11/04/2021

TP VEHICLE NO : SLL7627R

TAX INVOICE

NO : AR202105-0004

CLAIM NO

: QUOT202104-000028(01)

DATE

: 04/05/2021

POLICY NO

: 999995580

VEH REG

: SMQ4697U MAKE/MODEL : MERCEDES BENZ GLC200

(R18 LED)

CHASIS NO

: WDC2539422F672007

265.58

S\$4,059.58

ENGINE NO

: 27492031880677

REG. DATE

: 2019

ADD GST @ 7%:

GRAND TOTAL:

Final Repair Cost to Vehicle No: SMQ4697U

	Description	Quantity	List Price	Amoun
			<u>S\$</u>	S
	NET PRICE			
1	Rear bumper (upper)	1	960.00	960.00
2	Rear bumper (lower)	1	558.00	558.00
3	Rear bumper reinforcement	1	812.00	812.00
4	Rear bumper reflector - RH	1	33.00	33.00
5	Rear bumper sensor seals	6	12.00	72.00
6	Rear bumper lower chrome	1	510.00	510.00
7	Rear bumper tow cover	1	65.00	65.00
8	Rear exhaust end chrome - RH	1	450.00	450.00
			_	3,460.00
			Less 10%	346.00
			Accounts	3,114.00
	SPECIAL NET			
9	Rear bumper clips (set)	1	50.00	50.00
			_	50.00
	LABOUR			
10	To remove and refix rear bumper sensor	1	60.00	60.00
11	To check and rectify wiring system	1	20.00	20.00
12	To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessry, to refit adjust the same.	1	300.00	300.00
13	To putty and spray paint on affected areas	1	250.00	250.00
				630.00
-			TOTAL:	\$\$3,794.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Website: www.tlauto.com.sg Email: operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-02 **IOB BUILDING**

SINGAPORE 049711

ATTN: MOTOR CLAIMS DEPT

TEL: 6849 8118

FAX:

YOUR REF NO : SLL7627R

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 11/04/2021

TP VEHICLE NO : SLL7627R

NO : AR202105-0004

CLAIM NO : QUOT202104-000028(01)

DATE POLICY NO : 04/05/2021

: 999995580

VEH REG

: SMQ4697U

MAKE/MODEL

: MERCEDES BENZ GLC200

(R18 LED)

CHASIS NO

: WDC2539422F672007

ENGINE NO

: 27492031880677

REG. DATE

: 2019

Final Repair Cost to Vehicle No: SMQ4697U

List Price Description Quantity **Amount** S\$ 5\$

TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

E. & O.E.

> Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

15 Apr 2021 / 16:01:29

Receipt Date/Time : 15 Apr 2021 / 16:01:29

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210415-002594

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLL7627R As at 11 Apr 2021/11:20:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Co: MSIG INSURANCE (SINGAF 1 Insurance Enquiry - SLL7627R	PORE) PTE LTD - 31 12/-	2020		
Enquiry Fee 20210415160002038431		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	518834XXXXXX2002	eNETS (Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Merimen e-Claims

View Received Message

This mail is associated with:

*SMQ4697U (MFL2021D0001680) [SLL7627R]

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Apr 11 2021 11:00AM

> [-] Tong Luck Auto Pte Ltd

Reply	Reply All Mark as Unread Print Message Delete Message Forward	
From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/08/2021 17:16 PM.		
То	LKK_HQ	
Subject	bject Alert - Adj Mandate Approved (S\$4667.03) - SMQ4697U - Claim Handler: Derrick Tan Ming Chye	

Approved:4667.03:Dear Sir, please proceed with direct settlement and also upload the before paint photos. Thank you.

DOCUMENTS SUMMARY

There are no documents.