

ASS. REC. BY:

REF:

210048331/kv

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 01/29 Person Contacted: _____ Vehicle: IN / OUTVeh No: SFR 3111C Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Toy Wish c.c. 1794Colour: B.P. White A/C: Insured / Std / NI / NASp. Reading: 212583 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W 003001649Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 14/4/21Survey held at 19/4/2021Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5 11:00 AM @ 45501 Cebu

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Papers

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

GST Reg. No.: 201113667N

Not Notified
6/1 Day @ 4550/r
Recovery after Pain
5 days

150.00 120%

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SKR4878H

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

100.00 *601*

To putty and spray replaced parts

1,200.00 *7501*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *6001*

Total : S\$ 7,457.65

=====

Singapore Dollars Seven Thousand Four Hundred
and Fifty Seven and Cents Sixty Five Only