# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Alfred Toh Date: 26 Apr 2021

# **Preliminary Advice**

Insured Vehicle No : XE117L

TP Vehicle No : SLM8337R Accident Date : 14/04/2021
Make : TOYOTA PRIUS HYBRID Assignment Date : 19/04/2021

Date of Inspection : 19/04/2021 Est. Duration of Repair : 6

Inspection At : LION CITY RENTAL (JALAN LAM HUAT ) (HQ)

60 JALAN LAM HUAT, 04-35/36 CARROS CENTRE

SINGAPORE 737869

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,797.28
Revised Amount	:S\$	4,773.43
Check Items (Estimated)	:S\$	5,253.83
Total	:S\$	10,027.26

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(	)	Other comments :