



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL	Ref: CS/SMO21004880/Kqf3
50 RAFFLES PLACE #03-03	Date: 19/04/2021
SINGAPORE LAND TOWERSINGAPORE 048623	Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 3753A	Veh. Inspected	SHB 1235C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101218/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	19/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/04/2021	Inspection Date	19/04/2021
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			